

FIG. 1




FIG. 2




FIG. 3




FIG. 4

ı	[0.1000]	1	[0.1 .0 6]	
Reference Signal Strengths =	[0.1000]	Reference Gain Adjusting Factors =	3.1623	
	0.1250		2.8284	
	0.1500		2.5820	
	0.1750		2.3905	
	0.2000		2.2361	
	0.2250		2.1082	
	0.2500		2.0000	
	0.2750		1.9069	
	0.3000		1.8257	
	0.4000		1.5811	
	0.5000		1.4142	
	0.6000		1.2910	
	0.7000		1.1952	
	0.8000		1.1180	
	0.9000		1.0541	
	1.0000		1.0000	
	1.1000		0.9535	
	1.2000		0.9129	
	1.3000		0.8771	
	1.4000		0.8452	
	1.5000		0.8165	
	1.6000		0.7906	
	1.7000		0.7670	
	1.8000		0.7454	
	1.9000		0.7255	
	[2.0000]		0.7071	

FIG. 5





FIG. 6



Reference Gain Adjusting Factors

FIG. 7




FIG. 8




FIG. 9